HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Barnes-Brinton House South side of U.S. Route 1 (Baltimore Pike), .6 mile east of Hickory Hill Road, approximately 2 miles west of Chadds Ford Chadds Ford Vicinity (Pennsbury Township) Chester County Pennsylvania

HABS No. PA-173

Documentation: 5 exterior photos (1959)

12 interior photos (1959)

1 exterior photocopy of circa 1905 photo

5 data pages (1959)

PA-173-1	Ned Goode, Photographer SOUTH FRONT	April 1959
PA-173-2	Ned Goode, Photographer EAST SIDE	April 1959
PA-173-3	Ned Goode, Photographer NORTH SIDE	April 1959
PA-173-4	Ned Goode, Photographer WEST SIDE	April 1959
PA-173-5	Ned Goode, Photographer WEST SIDE, GABLE END	April 1959
PA-173-6	Ned Goode, Photographer FIRST FLOOR, WEST ROOM,	=
PA-173-7	Ned Goode, Photographer FIRST FLOOR, WEST ROOM,	
PA-173-8	Ned Goode, Photographer FIRST FLOOR, WEST ROOM,	April 1959 NORTHWEST CORNER, SHOWING STAIRWAY
PA-173-9	Ned Goode, Photographer FIRST FLOOR, EAST ROOM,	
PA-173-10	, , ,	April 1959 NORTHEAST CORNER, SHOWING CLOSET WITH

WINDOW AND SEAT

Barnes-Brinton House HABS No. PA-173 (Page 2) Index to Photographs

- PA-173-11 Ned Goode, Photographer April 1959 SECOND FLOOR, WEST ROOM, WEST WALL
- PA-173-12 Ned Goode, Photographer April 1959
 SECOND FLOOR, WEST ROOM, SOUTHWEST CORNER, SHOWING CLOSET
 AND GRILLWORK
- PA-173-13 Ned Goode, Photographer April 1959 SECOND FLOOR, EAST ROOM, EAST WALL
- PA-173-14 Ned Goode, Photographer April 1959 SECOND FLOOR, EAST ROOM, EAST WALL, SHOWING DETAIL OF GRILLWORK
- PA-173-15 Ned Goode, Photographer April 1959
 SECOND FLOOR, EAST ROOM, SOUTHEAST CORNER, SHOWING STAIRWAY
- PA-173-16 Ned Goode, Photographer April 1959 SECOND FLOOR, EAST ROOM, WEST WALL, SHOWING DOOR TO CENTER ROOM
- PA-173-17 Ned Goode, Photographer April 1959 BASEMENT, NICHE IN NORTH WALL
- PA-173-18 Photocopy of photograph (original print in Chester County Historical Society, West Chester, Pennsylvania)
 Circa 1905, photographer unknown
 SOUTH FRONT AND WEST SIDE